



Casitas at NORTHTOWN




3RD FLOOR

BAY WINDOW
CONDITION
L

WINDOW
CONDITION
L1



2ND FLOOR



MAIN FLOOR

UNIT No.

TYPE L	TYPE L1
1006	1002 1307
1110	1009 1313
1310	1028 1502
1506	1103 1512
1522	1107 1519
	1113 1526
	1303 1529
	1636

TYPE L & L1
3 BEDROOM

Purchaser Acknowledgement _____ Date _____

Casitas (Municipal) No. _____

Level _____ Unit No. _____

TRIDEL

Dimensions and specifications subject to change.
Window sizes may vary slightly. Landscaping and
patio areas subject to change. E. & G.E.